

Table of Contents

Introduction	1
Who Should Read this Book?	1
Using AutoCAD for Design, Engineering, and Technical Drafting	2
2D versus 3D: Choosing the Right Tool for the Right Job	2
What You Need To Use this Book	2
DOS Version	2
UNIX, Macintosh, and Other Operating Systems	2
AutoCAD Version and Equipment	3
Compatibility with Earlier Versions of AutoCAD	3
How this Book Is Organized	4
The Optional AutoCAD: Drafting and 3D Design Drawing Disk	4
How To Use the ACAD Disk's Exercise Drawings	5
The Y14.5 Menu System	5
About this Book	5
Things To Watch For	5
How Exercises Are Shown	6
1 Hardware Tools for CAD	9
Overview	10
Understanding Input Devices	10
Keyboard	10
Mice and Digitizer Tablets	11
Selecting an Input Device	14
Using the Numeric Pad for Cursor Control	14
Understanding Disks and Disk Drives	15
Hard Disks	15
Floppy Disks	15
Backup Systems	16
Understanding Monitors	16
Display Resolution	16
Autosync Monitors	18
Ghosting or Cursor Trails	18
AutoCAD's Advanced User Interface (AUI)	18
Understanding Output Devices	20
Pen Plotters	20
Printer Plotters	21
Dot-Matrix Printers	22
Ink Jet, Thermal, and Laser Printers	22
Networking AutoCAD	23
Summary	23

2 AutoCAD Commands and Command Entry 25

Overview	26
Booting Up to AutoCAD's Main Menu	26
Using AutoCAD's Main Menu Options	26
Drawing File Names	29
File Utilities Menu	29
Getting To Know AutoCAD's Drawing Editor Menus	30
Accessing the Screen Menu	31
Applying Screen Menu Rules	31
Selecting Menu Items from the Keyboard	33
Using Pull-Down Menus	33
Using Dialogue Boxes	35
Using Scroll Bars	36
Using Icon Menus	36
Using Toggles and Function Keys	37
Giving Commands to the Drawing Editor	38
Selecting Defaults and Entering Values	39
Using Transparent Commands	39
Correcting Data Entry Errors	40
Undoing Mistakes	41
Summary	41

3 Starting a Drafting Project 43

Overview	44
Establishing Parameters and Values for PART1	45
Entering the Drawing Editor	45
AutoCAD's Automatic Drawing Setup	46
Selecting a Unit of Measure	48
Setting the Drawing Aids	50
Setting Drawing Tools Using the Screen Menus	51
Setting Drawing Tools with a Dialogue Box	52
Navigating Using AutoCAD's Coordinate System	54
The User Coordinate System Icon	55
Absolute Coordinates	56
Relative Coordinates	56
Polar Coordinates	57
Integrating Absolute, Relative, and Polar Coordinates	59
The Coordinate Readout	59
Drafting a Part	60
Drawing an Object with Lines and Circle	61
Using Text Tools	63
Applying Text Justification	64
Editing Text Using a Dialogue Box	67
Inserting Text Control Codes	68
Using Various Text Styles	70
Saving and Quitting	73
Getting Help When You Need It	74
Asking for Assistance about Specific Commands	76

Using Drafting Inspection Tools	77
Using AutoCAD's Built-in Calculator	80
Saving and Exiting the Drawing Editor	80
Summary	82

4 AutoCAD's Line Conventions 83

Overview	84
Establishing Parameters and Values for PART2	85
Understanding Polylines	86
Drawing the PART2 Profile	87
Assigning Linetypes and Colors	89
Choosing Entity Linetypes	90
Changing the Linetype To Draw Hidden Lines	93
Using Linetype Scale	93
Establishing Entity Colors	94
Changing a Drawing's Linetypes and Colors	95
Summary	100

5 Drawing and Erasing Simple Entities 101

Overview	102
Establishing Parameters and Values for PART3	103
Drawing the PART3 Profile	104
Drawing the Circles	105
Redrawing the Screen	106
Drawing Arcs	107
Using Object Selection and Erasing Techniques	109
Applying AutoCAD's Object Selection	110
Selecting Objects for Erasing	111
Using Oops To Replace Mistaken Erasures	112
Using the Window and Crossing Options To Erase	113
Using the U, Undo, and Redo Commands	114
Summary	117

6 Drafting In TILEMODE Model Space 119

Overview	120
Beginning the Drawing	121
Setting Up Multiple Viewports in TILEMODE Model Space	122
Controlling the Screen Display with Pan and Zoom	124
Displacing the Drawing Using Pan	125
Taking a Closer Look Using Zoom	126
Drawing the PART4 Profile	128
Drawing Polygons	131
Saving and Restoring Views	132
Saving and Restoring Viewport Configurations	136
Summary	139

7 Drafting in Paper Space	141
Overview	142
Establishing Parameters and Values for PART5	142
Drawing the Object Profile	144
Adding Ellipses	145
Using Paper Space Tools for Drafting	146
Creating Viewports in Paper Space	147
Metaview Options	148
Using Model Space with TILEMODE Off	150
Using Multiple Viewports in Paper Space	152
Magnifying Objects Relative to the Paper Space Scale	154
Saving a Viewport as a View	158
Stretching Entities or Selection Sets	158
Moving Entities	162
Using Paper Space Viewports To Create Drawings	163
Plotting Your Drawings	165
Summary	170
8 Prototype Drawings	171
Overview	172
Creating a Generic Drafting Prototype	173
Starting the Drawing and Setting the Limits	174
Setting and Changing System Variables	175
Getting the Prototype Ready for Dimensioning	179
Saving a Dimensioning Style	182
Creating a Border and Title Block	182
Drafting a Polyline Border	184
Setting a User Coordinate System	185
Organizing Layers with Linetypes and Colors	186
Using the Modify Layer Dialogue Box	188
Using the Layer Command	191
Listing Layers	192
Changing the Current Layer	193
Using a Title Block Format	194
Drawing the Main Title Block	195
Establishing Standards for General Notes	201
Controlling Layer Status	202
Paper Space Viewport Layer Control	203
Dialogue Paper Space Viewport Layer Control	204
Startup Layer Status for the Prototype	204
Saving a View ALL	205
Creating a Paper Space Bordered Sheet and Title Block	206
Checking and Ending the Prototype	207
Setting Up a Scratch View and UCS	208
Organizing Multiple Prototypes	212
Scaling for Plotting	213
Scale Factor Settings	214
Adjusting Settings and Graphics for Scale	215
Summary	215

9 2D Orthographic Drafting and Advanced Editing 217

Overview	218
Using Multiple Viewports	219
Drafting the BRACKET Profile	223
Working in a Temporary UCS	225
Editing by Breaking the BRACKET Drawing	227
Picking Precise Geometric Positions Using Object Snap	229
The Object Snap Command	234
Trimming Entities	234
Extending Lines	236
Mirroring the Bracket	241
Summary	243

10 Dimensioning Engineering Drawings 245

Overview	246
Using AutoCAD'S Built-In Dimensioning	247
Associative Dimensioning	249
Customizing Dimensioning	249
Setting Dimensioning Variables from the Pull-Down Menu	250
Dimensioning Flexibility Leads to Choices	250
Recommended Spacing for Dimensions	252
Dimensioning in Model Space and Paper Space	252
Dimensioning the Bracket Drawing	253
Linear Dimensioning	254
Editing Dimension Text	256
Drafting with Tolerances	258
Updating Dimensions	259
Selecting Entities To Dimension	260
Vertical and Continue Dimensions with Tolerances	260
Continuous (Chain) Dimensions	261
Controlling Dimension Text	263
Baseline Dimensioning	263
Diameter Dimensions with Tolerances	264
Completing the Bracket—Optional	266
Summary	268

11 Creating a Multi-Detail Working Drawing—Phase 1 ... 269

Overview	270
Understanding Parts and Parts Libraries	271
Drafting the Arm	272
Copying Entities and Selection Sets	274
Constructions with Point Filters	276
Filletting the Arm	280
Dimensioning the Arm	282
Radius Dimensioning	282
Associative Dimensioning	284
Associative Dimensioning Variables	285
Exploding Associative Dimensions	285

Stretching and Scaling Associatively Dimensioned Geometry	286
Updating Associative Dimensions	288
Completing the Arm's Dimensions—Optional	289
Blocking Entities into Groups	291
Writing the Arm to Disk	293
Drafting the Spacing Pin	295
Chamfering Geometry	297
The Pin's Right Side View—Optional	300
Dimensioning the Pin	301
Pointing to Specific Locations with Leaders	303
Completing the Pin's Dimensions—Optional	305
Write Blocking the Pin to Disk	306
Drafting the Servo Motor Mount	306
Rectangular Arrays	308
Completing the Two Views—Optional	310
Dimensioning Circles to ANSI Standards	311
Completing the Mount's Dimensions	313
Writing the Mount to Disk	315
Drafting the Adjustment Plate	315
Inserting Pre-Exploded Blocks	316
Changing Existing Entities	319
Developing Line-Arc Continuations	322
Completing the Plate's Dimensions—Optional	325
Drafting the Pulley	327
Polar Arrays	380
Hatch and Pattern Filling	335
Hatch Pattern Icon Menus	336
Hatch Options	337
Hatch Styles	337
Hatch and Pattern Boundaries	338
Dimensioning the Pulley	344
Angular Dimensioning	344
Suppressing Extension Lines	346
Cutting Planes	350
Finishing the Pulley—Optional	352
Writing the Pulley to Disk	353
Summary	354

12 Creating a Multi-Detail Working Drawing—Phase 2 ... 355

Setting Up and Drafting the Robot Arm	356
Drawing Setup	357
Inserting Blocks	361
Editable Block Inserts	361
Block Scale and Rotation	362
Editing the B-ARM Dimensions—Optional	363
Insertion and DIMLFAC	364
Insertion and Scratch Block Redefinition	364
Numbering and Labeling the Parts and Title Block	365
Plotting the Multi-Detail Drawing	366
Summary	370

13 Creating Symbol Libraries and Attributes	371
Overview	372
Building Smart Symbols with Attributes	374
Attributes: Intelligent Symbol Text	375
Defining an Attribute	376
Including Attributes in Blocks	377
Editing Attribute Definitions	378
Inserting Attribute-Laden Blocks	378
Presetting Block Scale and Rotation	380
Editing Attributes	381
Attribute Editing and Insertion by Dialogue Box	384
Attribute Entry by Dialogue Box	384
Using the Y14.5—GDT Symbol Library	385
Creating Parts and Extracting Their Data	387
Attribute Modes	389
Attribute Selection Order	392
Invisible, Constant, Verify, and Preset Inserts	393
Controlling Attribute Visibility	393
Extracting Attribute Information	395
Working with Template Files	397
Summary	399
14 Applying Geometric Dimensioning and Tolerancing .	401
Overview	402
Drawing the M-COUPLE in Two Views	402
Drawing the M-COUPLE Front View	403
Drawing the M-COUPLE Section View	405
Following Steps and Rules for Production Dimensioning	409
Using Geometric Dimensioning and Tolerancing Steps	410
Establishing Dimensioning Datum Locations	411
Locating Holes and Slots	413
Locating and Sizing Features	415
Giving Overall Sizes	417
Sizing Holes	418
Adding Feature Control References, Symbols, and Finish Marks	419
Adding to the General Notes	423
Summary	425
15 3D Extrusion Drafting	427
Overview	428
Setting Up a Prototype for 3D	429
Using Viewpoints for Simultaneous 2D and 3D Views	431
Drawing with 3D Extrusions	434
Thickness Makes the Extrusion	436
Elevation, Thickness, UCSs, and Construction Planes	437
Drawing above and below the WCS Construction Plane	437

Hidden Line Removal	439
Hidden Line Removal Speed	440
Hiding and Plotting	441
Where Do Hidden Lines Go?	441
Shading 3D Images	441
Shade Options	442
Shading Reflection and Ambient Light—SHADEDIF	442
Solidifying Extrusions	443
Editing Polylines with the Pedit Command	446
Extruding a Hexagon Bolt	449
Covering Surfaces with the 3Dface Command	451
Setting Up for Plotting	454
Checking Scale and Alignment of Views	454
Setting Up ANSI Drawing Sheets	455
Using Mvsetup with TILEMODE Off	455
Freezing Viewport Frames for Plotting	458
Summary	460

16 3D Wireframe and Mesh Modeling 461

Overview	462
The User Coordinate System	463
3D Techniques for the Angle Support	465
Drawing the Construction Envelope	466
2D and 3D Polylines	470
Developing the Angle Base Profile	471
3D Polygon Mesh Surfaces	472
Controlling Mesh Density (Surface Tabulation)—Surftab	474
Tabulated Surfaces—Tbsurf	474
Extending the Base with Tbsurf	475
Surfaces of Revolution—Revsurf	476
Right Hand Rule—Direction of Rotation	479
Tabulated Surfaces—Tbsurf	480
Polygon Faces—Pface	484
Making Invisible Edges on Pfaces	485
Closing the Base's Top and Bottom — Optional	488
Edge Defined Coons Surface Patch—Edgesurf	488
Challenge Exercise—Optional	488
Summary	489

17 3D Manipulations 491

Overview	492
Creating Orthographic and Parallel Projection Views	492
Viewing 3D Drawings Using the Dview Command	493
Using the Dview Camera	496
Using the Dview Points Option	501
Using Dview Distance, Pan, and Zoom	505
Inserting Captured Blocks	509

Editing the Views into 2D	512
Purging Blocks, Layers, Linetypes, Shapes, and Styles	517
Cleaning Up the 3D View—Optional	517
Completing the 2D Front and Auxiliary Views—Optional	518
Dimensioning 2D Views	520
Creating a Multi-View Drawing in Paper Space	520
The Command Set for Paper Space Viewports	521
Dimensioning a 3D View	534
Summary	540

18 Advanced 3D Surface Modeling 541

Overview	542
Modeling the U-Joint Cap	543
Modeling the Yoke	544
Modeling the U-Joint	547
Creating a 3D Exploded Illustration	549
Summary	550

A DOS, Batch Files, and Text Editors 551

Working with Files	551
Using DOS Directory Commands To Manage Files and Directories	552
Navigating through Directories (DIR)	553
Creating Directories (MD or MKDIR)	553
Changing Directories (CD or CHDIR)	553
Saving AutoCAD Drawing Files in Subdirectories	555
Using Path Commands	555
Removing Directories (RD or RMDIR)	555
Using DOS File Commands	556
Copying Files (COPY)	556
Comparing Files (COMP)	557
Deleting Files (DEL)	557
Renaming Files (REN)	557
Using DOS Disk Commands	558
Changing the Default Drive	558
Checking Disks (CHKDSK)	558
Copying Floppy Disks (DISKCOPY)	559
Comparing Floppy Disks (DISKCOMP)	559
Formatting Disks (FORMAT)	560
Creating a Bootable Disk Using the FORMAT /S Command	560
Formatting with Volume Labels (FORMAT /V)	560
Displaying Directory Trees (TREE)	561
Setting Environment Variables (SET)	561
Creating Batch Files	561
Understanding the Automatic Executing .BAT File (AUTOEXEC.BAT)	562
Selecting Text Editors	562

B Systems, Setup, Memory, and Errors	565
Using AutoCAD on DOS-Based, Unix-Based, and Other Systems	565
Understanding the General System Components	566
Setting Up AutoCAD in a DOS Environment	566
Using Extended and Expanded Memory	567
Loading DOS Programs on a Hard Disk	567
The CONFIG.SYS File	568
The AUTOEXEC.BAT File	569
Setting Up AutoCAD	570
Creating a Subdirectory for AutoCAD	570
Configuring AutoCAD	570
Starting AutoCAD	571
Setting Up for AutoCAD: Drafting and 3D Design	571
Creating the D3D-ACAD Subdirectory in a UNIX Environment	572
Installing the AutoCAD: Drafting and 3D Design Disk	572
Copying the AutoCAD Configuration and Overlay Files	573
Automating AutoCAD Startup Using ACAD.BAT	573
Testing ACAD.BAT	574
Creating a Default ACAD.DWG	574
Automating AutoCAD with a UNIX Script	575
C AutoCAD Command List	577
Selecting Objects in AutoCAD	577
Picking Points Using Coordinates	578
AutoCAD Commands	579
Using the AutoLISP 3D Programs	607
Index	613